**** MATERIAL SAFETY DATA SHEET ****

Version Date......09/08/10 26 ALUMINUM WELDING FILLER ALLOY Print Date...........09/08/10 SECTION 1 PRODUCT IDENTIFICATION COMPANY NAME WHO SENT MSDS..... HARRIS PRODUCTS GROUP COMPANY ADDRESS..... 4501 QUALITY PLACE MASON OHIO 45040 (513) 754-2000 EMERGENCY PHONE NUMBER..... (800) 424-9300 MSDS VERSION NUMBER..... TRADE NAME..... HARRIS 26- ALUMINUM WELDING FILLER ALLOY HAZARD RATING (HMIS)...... HMIS DESIGNATION KEY..... NA SECTION 2 HAZARDOUS COMPONENTS MATERIAL § BY WEIGHT CAS NUMBER OSHA PEL ACGIH TLV (Mq/M3) SEC 313 ALUMINUM 70-80 7429-90-5 NOT REGISTERED YES 7440-03-1 SILICON 1-11 3 AS SiO2 NA ALUMINUM FLUORIDE 1-11 7784-18-1 2.5as F,2 as Al YES LITHIUM FLUORIDE 1-11 7789-24-4 2.5 as F NA 1-11 7783-40-6 MAGNESIUM FLUORIDE 2.5 as F NA 7447-40-7 POTASSIUM CHLORIDE 1-11 NOT REGISTERED NA POTASSIUM FLUORIDE 2-12 7789-23-3 2.5 as F NA SODIUM CHLORIDE 1-11 7647-14-5 NOT REGISTERED SECTION 3 PHYSICAL PROPERTIES BOILING POINT.... NA MELTING POINT.... VAPOR PRESSURE........ NA VAPOR DENSITY (AIR = 1)..... NA SOLUBILITY IN WATER..... SPECIFIC GRAVITY..... NA EVAPORATION RATE..... NA APPEARANCE AND ODOR...... COATED METAL ROD. NO ODOR. __________ SECTION 4 FIRE AND EXPLOSION DATA FLASH POINT..... NA

26 ALUMINUM WELDING FILLER ALLOY

SECTION 4 FIRE AND EXPLOSION DATA

EXTINGUISING MEDIA..... SEE BELOW

SPECIAL PROCEDURES..... SEE BELOW

WELDING ARC AND SPARKS CAN IGNITE COMBUS-UNUSUAL HAZARDS.....

TIBLES AND FLAMMABLES. REFER TO AMERICAN NATIONAL STANDARD Z49.1 FOR FIRE PREVEN-TION DURING THE USE OF WELDING AND ALLIED

CONT'D

PROCEDURES

SECTION 5 REACTIVITY DATA

STABILITY..... STABLE

CONDITIONS TO AVOID..... NONE UNLESS OTHERWISE SPECIFIED

HAZARDOUS POLYMERIZATION..... INCOMPATABILITY..... NONE

HAZARDOUS DECOMPOSITION PRODUCTS

THE COMPOSITION AND QUALITY OF WELDING FUMES AND GASES ARE DEPENDENT UPON THE METAL BEING WELDED, THE PROCESS, PROCEDURE AND ELECTRODES USED. OTHER CONDITIONS WHICH ALSO INFLUENCE THE COMPOSITION AND QUANTITY OF FUMES AND GASES TO WHICH WORKERS MAY BE EXPOSED INCLUDE: COATINGS ON METAL BEING WELDED (SUCH AS PAINT, PLATING, OR GALVANIZING), THE NUMBER OF WELDERS AND VOLUME OF THE WORK AREA, THE QUALITY AND AMOUNT OF VENTILATION, THE POSITION OF WELDER'S HEAD WITH RESPECT TO FUME PLUME, AND THE PRESENCE OF CONTAMIN-ANTS IN ATMOSPHERE (CHLORINATED HYDRO-CARBON VAPORS FROM CLEANING AND DEGREASING ACTIVITIES). WHEN ELECTRODE IS CONSUMED, THE FUME AND GAS DECOMPOSITION PRODUCTS GENERATED ARE DIFFERENT IN PERCENT AND FORM FROM INGREDIENTS IN SECTION 2. FUME AND GAS DECOMPOSITION PRODUCTS, AND NOT INGREDIENTS IN ELECTRODE, ARE IMPORTANT. CONCENTRATION OF GIVEN FUME OR GAS COMPON-ENT MAY DECREASE OR INCREASE BY MANY TIMES ORIGINAL CONCENTRATION. NEW COMPOUNDS IN ELECTRODE MAY FORM. DECOMPOSITION PRO-DUCTS OF NORMAL OPERATION INCLUDE THOSE ORIGINATING FROM VOLATILIZATION, REACTION, OR OXIDATION OF MATERIALS IN SECTION 2. PLUS THOSE FROM BASE METAL AND COATING, ETC., AS NOTED ABOVE. REASONABLY EXPECTED FUME CONSTITUENTS OF PRODUCT COULD INCLUDE PRIMARILY OXIDES OF IRON; SECONDARILY OXIDES OF CHROMIUM, NICKEL, MANGANESE, SILICON, AND MOLYBDENUM. PRESENT OSHA EXP. LIMITS FOR HEXAVALENT-CHROMIUM IS

26 ALUMINUM WELDING FILLER ALLOY

SECTION 5

_______ REACTIVITY DATA

CONT'D

.05 MG/M3 AND NICKEL 1MG/M3 WHICH WILL RE-SULT IN SIGNIFICANT REDUCTION FROM 5MG/M3 GENERAL FUME LEVEL. GASEOUS REACTION IN PRODUCTS MAY INCLUDE CARBON MONOXIDE AND CARBON DIOXIDE. OZONE AND NITROGEN OXIDES MAY BE FORMED BY THE RADIATION FROM ARC. IN ADDITIOIN TO SHIELDING GASES LIKE ARGON AND HELIUM WHEN EMPLOYED. ONE RECOMMENDED WAY TO DETERMINE COMPOSITION AND QUANTITY OF FUMES AND GASES OT TO TAKE AIR SAMPLE FROM INSIDE WELDER'S HELMET IF WORN OR IN BREATHING ZONE. SEE AWS F1.1 AND AWS F1.2 -1985, AVAILABLE FROM THE AMERICAN WELDING SOCIETY. SEE AWS PUBLICATION: "FUMES AND GASES IN THE WELDING ENVIRONMENT".

SECTION 6 HEALT	H HAZARD DATA
ROUTES OF ENTRY	INHALATION, SKIN AND INGESTION ELECTRIC ARC-WELDING MAY CREATE: FUMES AND GASES CAN BE DANGEROUS. ARC RAYS CAN INJURE EYES AND BURN SKIN. ELECTRIC SHOCK CAN KILL.
CARCINOGENICITY	THE ACGIH RECOMMENDED GENERAL LIMIT FOR WELDING FUME NOC IS 5 MG/M3. ACGIH 1984-85 PREFACE STATES: THEE TIV-TWA SHOU BE USED AS GUIDES IN ONTROL OF HEALTH HAZARDS & SHOULD NOT BE USED AS FIRM LINES BETWEEN
SIGNS & SYMPTOMS OF EXPOSURE	CARCINOGENITY CONT SAFE AND DANGEROUS CONCENTRATIONS. SEE SECTION V FOR SPECIFIC FUME CONSTITUENTS WHICH MAY MODIFY THIS TLV.
MEDICAL CONDITIONS FROM EXPOSURE	SHORT TERM TO WELDING FUMES-DIZZINESS, NAUSEA, DRYNESS & IRRITATION OF NOSE, EYES THROAT, CHEST TIGHTNESS, FEVER, ALLERGIC REACTION. LONG TERM-SIDEROSIS, BELIEVED
EMERGENCY & FIRST AID	TO AFFECT PULMONARY FUNCTION. CALL FOR MEDICAL AID. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY THE AMERICAN RED CROSS.
ADDITIONAL INFORMATION	NA

SECTION 6 HEALTH HAZARD DATA CONT'D

#=====================================	
SECTION 7 PRECAUTIONS FOR SAFE HANDLING AND USE	
SPILL AND LEAK PROCEDURES	NA
WASTE AND DISPOSAL METHOD	PREVENT WASTE FROM CONTAMINATING SURROUND-ING ENVIRONMENT. DISCARD ANY PRODUCT RESIDUE, DISPOSABLE CONTAINER OR LINER IN ENVIRONMENTALLY ACCEPTABLE MANNER, IN FULL COMPLIANCE WITH FEDERAL, STATE, AND LOCAL REGULATIONS.
HANDLING AND STORING PRECAUTIONS	USE EXHAUST SYSTEM. MAKE SURE INHALED AIR DOES NOT CONTAIN FUME CONSTITUENTS ABOVE PERMISSIBLE EXPOSURE LEVELS. OTHER PRECAUTIONS FOR ADDITIONAL SAFETY INFORMATION ON WELDING AND CUTTING, SEE AMERICAN STANDARD Z49.1-1983, SAFETY IN WELDING AND CUTTING, AND THE WELDING HANDBOOK, VOL. 1, CHAPTER 9, SAFE PRACTICES IN WELDING AND CUTTING, BOTH AVAILABLE FROM AM WELDING SOCIETY INC., 550 N.W. LEJNUE RD.,
OTHER PRECAUTIONS	PO BOX 351040, MIAMI, FL 33135. PHONE 305-443-9353. READ AND UNDERSTAND MANUFACTURER'S INSTRUCTIONS AND THE PRECAUTIONARY LABEL ON THIS PRODUCT. SEE AM. NATIONAL STANDARD Z-49.1, SAFETY IN WELDING AND CUTTING BY THE AM. WELDING SOCIETY; AND OSHA PUBLICATION 2206 (29CRF 1910), U.S. GOVERNMENT PRINTING OFFICE FOR MORE DETAIL ON THE CONTROL MEASURES.
	ROL MEASURES
RESPIRATORY MEASURES	USE RESPIRABLE FUME RESPIRATORY OR AIR SUPPLIED RESPIRATOR WHEN IN CONFINED SPACE OR LOCAL EXHAUST DOES NOT KEEP EXPOSURE

VENTILATION.....

BELOW RECOMMENDED EXPOSURE LIMIT

USE ENOUGH LOCAL VENTILATION, AND LOCAL EX-

HAUST AT ARC TO KEEP FUMES AND GASES FROM WORKER'S BREATHING ZONE AND GENERAL AREA. TRAIN WORKER TO KEEP HEAD OUT OF FUMES

26 ALUMINUM WELDING FILLER ALLOY

CONTROL MEASURES CONT'D SECTION 8 PROTECTIVE GLOVES..... SEE OTHER PROTECTIVE EQUIPMENT WEAR HELMET, FACE SHIELD WITH FILTER LENS, EYE PROTECTION..... PROTECTIVE SCREENS, FLASH GOGGLES TO SHIELD OTHERS. START WITH SHADE TOO DARK THEN GO TO LIGHTER SHADE WHICH GIVES SUFF-ICIENT VIEW OF WELD ZONE. OTHER PROTECTIVE EQUIPMENT..... HAND, HEAD, BODY PROTECTION TO PREVENT IN-JURY FROM RADIATION, SPARKS AND ELECTRICAL SHOCK. DO NOT TOUCH LIVE ELECTRICAL PARTS AND INSULATE FROM WORK AND GROUND. WORK/HYGIENIC PRACTICES..... FOR MAXIMUM SAFETY: BE CERTIFIED FOR, AND WEAR A RESPIRATOR AT ALL TIMES WHEN WELDING OR BRAZING. _______ **DISCLAIMER** SECTION 9 THIS DATA IS BELIEVED TO BE ACCURATE. HARRIS WEL SECTION 10 ADDITIONAL INFORMATION NA = NOT APPLICABLE

ADDITIONAL INFORMATION

SECTION 11